-					DPM 362	6-6	1482				
	44.4		ATERIAL SAF		SHEET For	a Approved Budget	i Me. 45-20338				
	ADVANCED COATINGS	818-579-6270									
SECTION !	ADDRESS (Number, Street, City, State, and ZIP Code)										
	4343 Temple City Blvd, Temple City, CA 91780  CHEMICAL NAME AND SYNONYMS  TRADE NAME AND SYNONYMS										
	Modified Vinyl	Semi-Gloss Texturing Enamel Blue									
	CHEMICAL FAMILY Modified Vinyl		FORMULA	44A-6							
	FEDERAL STOCK NUMBER (FSN) GROSS WEIGHT			LBS) QUISIDE PACKAGE DIMENSIONS (Inches)							
	MIL-STD-1341/NATIONAL FIRE PROTECTION ASSOCIATION STD 704M SIGNAL										
	FLAMMABILITY HEALTH REACTIVITY \$PECIFIC HAZARO										
	PAINTS, PRESERVATIVES, AND SOLVENTS	v <b>ð i</b> ume	THRESHOLD LIMIT VALUE (Unita)	ALLOYS	AND METALLIC COATINGS	7.	THRESHOLD LIMIT VALUE (Unita)				
	PIGMENTS	4.22		BASE META							
	CATALYST			ALLOYS							
	VEHICLE	18.95		METALLIC	CDATINGS						
	10LYENTS	76.00		FILLER ME	TAL ING OR CORE FLUX						
	ACCITIVES	0.83		OTHERS							
	OTHERS						OJOHZBRHT				
	By Total Volume of Solvents						LIMIT VALUE (Units)				
	Aliphatic Hydroca		1 - 7 - 7 - 7 - 7 - 7	8 3 (6)	·24.88.	100 PPM					
	Aromatic Hydrocar	•			7.49	200 PPM					
	Esters		1-1		13.63	5 PPM					
	Ketones					54.00	200 PPM				
	BOILING POINT (F.)	Not Det	termined	SPECIFIC GRAVITY (#10=1)		1.05					
YIYO	VAPOR PRESSURE (mm H4.)	Not Det	termined	PRECENT VOLATILE BY VOLUME (%)		76%					
באר מ	VAPOR DENSITY (AIR = 1)	Not Determined		EVAPORATION RATE (=1)		Not Determined					
	SOLUBILITY IN WATER	Insoluble									
ľ	APPEARANCE AND ODOR										
<u> </u>	Blue Dispersion with Distinct Solvent Odor.  FLASH POINT (Meined used)  FLASH POINT (Meined used)  FLASH POINT (Meined used)						XPLOSIVE LIMIT				
× -	44°F. TCC	LIMITS Not Determined Not Determined									
HAZAKUL	Water Fog, Foam, CO <sup>2</sup> and/or Dry Chemicals										
	SPECIAL FIRE FIGHTING PROCEDURES										
NOICO I	None UNUSUAL FIRE AND EXPLOSION HAZARDS										
	Concentrated vapors may be explosive.										
						•					

1	As indicated							
_ ₹	EFFECTS OF OVEREXPOSURE To Vapors: Might be irritating to eyes, nose and throat.							
LYO	Repeated excessive exposure may result in headache, dizziness, sleepiness and							
SECTION V HEALTH HAZARD DATA	nausea. Defatting to skin.							
SEC	Skin Contact: Wash with mild soap and water. Use emollient cream or lotion.							
НЕАСТ	Eye Contact: Wash with gentle stream of water for 5 minutes. See a doctor immediate y							
	Vapor Contact: Provide freash air and rest.							
	STABILITY CONDITIONS TO AVOID							
		UNSTABLE						
VI DATA		STABLE	Х					
SECTION VI	INCOMPATABILITY (Materials to svoid)							
5≥	HAZARDOUS DECOMPOSITION PRODUCTS							
SE	On buring w	ill produc	e cart	on monoxide	e, carbon	dioxide and acr	rid fumes.	
RE	HAZARDOUS	MAY OCCUR		CONDITIONS TO	AVOID			
	POLYMERIZATION	WILL NOT	v				4/4	
	STEPS TO BE TAK	EN IN CASE MA	X	IS RELEASED OF	SPILLED			
ES	Avoid sparks or open flames. Provide adequate ventilation. Wipe spillage and							
SECTION VII OR LEAK PROCEDURES	safely discard absorbent materials. Large spills should be diked and pumped							
N VI PRO	into waste tank							
₽×	into waste tank.							
SEC.	Landfill - Consult with local, state and/or federal waste regulations for							
.t. 0!	proper and safe disposal.							
SPILL	proper and sure disposars							
z	RESPIRATORY PR	OTECTION (Spec	cify type)	In closed	areas us	air respirator	s or air mask	
IAL TIO	suitable for organic vapors.							
RMA	VENTILATION	LOCAL EXHAU		required		SPECIAL USA AVDIOSIO	n-proof equipmer	
SECTION VIII - SPECIAL PROTECTION INFORMATION		MECHANICAL (		required		OTHER	m-proof equipmen	
70					T=v= ====			
ECT	Recommended				Splash-proof goggles. (Anzi Z87-1, 1968)			
SEC	OTHER PROTECTIVE EQUIPMENT							
	Impervious apron. Eyewash facility.							
SECTION IX SPECIAL PRECAUTIONS	Handle as a flammable liquid. Do not store near open flames nor combustion							
ē35[								
SPE	chambers.	chambers.						
2 2	VI BER FRECADITIONS							
	PROPER SHIPPING (Article) NAME DOT CLASSIFICATION							
XF	Paint UN 12		r				Flammable	
SECTION X	Red	DOT MARKING		Avoid spark	ks & open		ures kin & eye contac	t.
SE TRA	DOT PLACARD	14.74.094		E TAKEN IN TRA				
	Avoid open flames & sparks. Keep containter closed.							